





ZTSCSK1

Plug & Play 2-Way Speaker Upgrade Kit


190W MAX POWER 95W RMS

2x Speakers



2x Tweeters







2x Tweeter Adapters

2x Bottom Plates

2x Speaker Harness







2x Tweeter Harness

2x ZZF-LP4000

2x ZZF-HP4000-6











2x ZZF-HP5000-6



2x PG Badges





Quick Start Guide



Screw the speaker into the speaker adapter.



2

Connect the ZZF-LP4000 filter to the midbass speaker terminal.

Connect the ZZF-HP4000-6 to the tweeter terminal.



3

Connect the speaker harness to ZZF-LP4000 and ZZF-HP4000-6.

Red Wire = ZZF-LP4000 Blue Wire = ZZF-HP4000-6





Quick Start Guide



Put the tweeter into the tweeter bottom plate.



(5)

Attach the tweeter adapter to the front of the tweeter in the bottom plate.



6

Remove the OEM tweeter for the a-pillar.





Quick Start Guide



Install the new tweeter in the a-pillar.



8

Connect the ZZF-LP5000-6 filter to the tweeter.



(9)

Connect the tweeter harness to the ZZF-HP5000-6 filter.





Specifications

Speaker Type:	2-Way Speaker Kit	
Speaker Size:	6.5" (165mm) / 1" / 0.78"	
Frequency Response:	60Hz - 20kHz	
Power Handling (RMS):	95W	
Power Handling (MAX):	190W	
Impedance:	4Ω	
Sensitivity:	89dB (1W/1m)	
Fs:	62Hz	
Qts:	0.593	
Crossover:	Inline Crossovers	
1" (25mm) Voice Coil		
Polypropylene cone with rubber surround		



Fitment List

Make	Model	Year	Fitment
Scania	New Generation	2016 → (Next Gen)	Front Doors





Disclaimer

Always ensure the speaker is securely attached. Phoenix Gold accepts no responsibility for damage or injury in relation to inappropriate securing of this product.

Phoenix Gold Product Warranty

LIMITED WARRANTY ON SPEAKERS

Phoenix Gold warrants this product to be free of defects in materials and workmanship for a period of one (1) years from the original date of purchase. This warranty is not transferable and applies only to the original purchaser from an authorized Phoenix Gold dealer. Should service be necessary under this warranty for any reason due to manufacturing defect or malfunction, Phoenix Gold or it's Country distributor / reseller will (at its discretion) repair or replace the defective product with new or re-manufactured product at no charge. Damage caused by the following is not covered under warranty: accident, misuse, abuse, product modification or neglect, failure to follow installation instructions, unauthorized repair attempts, misrepresentations by the seller. This warranty does not cover incidental or consequential damages and does not cover the cost of removing or reinstalling the unit(s). Cosmetic damage due to accident or normal wear and tear is not covered under warranty.

© 2024 Phoenix Gold - www.phoenixgold.com